

## BUILDING SAFETY CERTIFICATE

No. 131

Dated: 15/7/2025

It is certified that the existing building MASS INTERNATIONAL SCHOOL (name of the building or premises) at BALLOPUR, EKMI ROAD, LAHERIASARAI DARBHANGA (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	GROUND FLOOR					

The building is owned/occupied by MASS INTERNATIONAL SCHOOL, EKMIHAT BALLOPUR (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of C.P.W.D., DARBHANGA (Name of Department Govt.) on 15/7/2025 (date of inspection) in the presence of Anupma Jha, Principal (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 15/7/2025 for a period of TWO years in accordance with rule and subject to compliance of the specific conditions as appended.

1. N.A
2. N.A
3. N.A
4. N.A

Inspected on 15/7/2025 by \_\_\_\_\_

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: \_\_\_\_\_

Name: SUNIL KUMAR

Designation: Assistant Engineer


Name & Address of Department/ Office: O/o the Assistant Engineer, Darbhanga Central Sub-Division, CPWD, Darbhanga.

**TO WHOMSOEVER IT MAY CONCERN**

This is to certify that the building of **Mass International School**, located at *Ekmi Ghat, Ballopur, Laheriasarai, Darbhanga*, has been physically inspected. At present, the building is constructed up to the **ground floor only** and is **currently in use for academic activities**.

Based on the visual assessment and structural condition observed during the site visit, it is found that the building is structurally sound and stable. It is capable of withstanding seismic forces corresponding to an earthquake of magnitude up to **5.0 on the Richter Scale**, as per the current condition and existing construction.

This certification is issued on the basis of physical verification only and does not include detailed structural analysis or laboratory/non-destructive testing.

  
29-07-2025

Assistant Engineer  
Darbhanga Central Sub-Division  
CPWD, Darbhanga.